



## Photo #2

US - California Proposition 65 - CRT: Listed date/Carcinogenic substance

Acrylamide (CAS 79-06-1) Listed: January 1, 1990 Carcinogenic.

US - California Proposition 65 - CRT: Listed date/Developmental toxin

Acrylamide (CAS 79-06-1) Listed: February 25, 2011 Developmental toxin.

US - California Proposition 65 - CRT: Listed date/Male reproductive toxin

Acrylamide (CAS 79-06-1) Listed: February 25, 2011 Male reproductive toxin.

## 6. Accidental Release Measures

Personal precautions Keep unnecessary personnel away. Keep people away from and upwind of spill/leak. Keep out of

low areas. Do not touch damaged containers or spilled material unless wearing appropriate protective clothing. Ensure adequate ventilation. For personal protection, see section 8 of the


MSDS. Material can be slippery when wet.

Environmental precautions Prevent further leakage or spillage if safe to do so. Do not flush into surface water or sanitary

sewer system.



Photo #3



**Photo #4.** Northern Pass inspector (in orange) looks on while S.W. Cole employees load open five gallon buckets of slurry into an open pick-up truck which is also holding an uncovered slurry tub. Location is next to a steep bank down to a stream. This truck drove south down Route 116 and through WMNF before ending where? What happened to the slurry? What would have happened in the event of an accident?



Photo #5.

Cleaning the boring rig near Wildwood Campground public water supply, WMNF, Easton.



**Photo** #6. Northern Pass contractor dumps slurry onto ground before hosing it into the undergrowth.

This location is next to the public water supply at Wildwood Campground, Easton.

No Safety Data Sheets on site. Does this man know he was working with a male reproductive toxin absorbed through the skin?

Is this Best Management Practices?



**Photo #7** Slurry tub overflow draining down Route 112, WMNF

**Photo #8** slurry frac-out to Stark Fall Brook, WMNF Woodstock



Photograph 1: "Mud bucket" set up for geotechnical borings.



Photo #9, May 2017 Easton


**Photo #10** 2016, Deerfield






**Photo #11**, Deerfield substation 2016.

## **Photo #12:**






BH-139

Ston





BH-36A Hole Collapsed 34'-39'BH-36C Lost Circulation 5', hole abandoned @ 34'

BH-37B Cobble at 21' and 26'-28' BH 40A Hole Collapsed 29'-35'



Photo #14, haybale from Stark Falls frac-out site, dumped in woods, WMNF.


NPT contractors S.W. Cole, Geosearch, PAR and Crux were unwilling to execute even the simplest BMPs while drilling 3" geotechnical boreholes.

How could they competently and safely drill two 18' HDD boreholes in each of the proposed 51 HDD locations?



**Photo #15:** 

**Photo #16: Paradise Falls, Lost River Gorge** 



Is Northern Pass willing to risk a frac-out into Lost River?

"The ordinary corporation is a "person" for purposes of the adjudicative processes, whether is represents proprietary, spiritual, aesthetic, or charitable causes.

So it should be as respects valleys, alpine meadows, rivers, lakes, estuaries, beaches, ridges, groves of trees, swampland, or even air that feels the destructive pressures of modern technology and modern life. The river, for example, is the living symbol of all the life it sustains or nourishes-- fish, aquatic insects, water ouzels, otter, fisher, deer, elk, bear, and all the other animals, including man, who are dependent on it or who enjoy it for its sight, its sound, or its life. The river as plaintiff speaks for the ecological unit of life that is part of it. Those people who have a meaningful relation to that body of water-- whether it be a fisherman, a canoeist, a zoologist, or a logger, must be able to speak for the values which the river represents and which are threatened with destruction."

Mr. Justice Douglas, dissenting in Sierra Club, v. Rogers C.B. Morton, Individually, and as Secretary of the Interior of the United State,s et al. (April 19<sup>th</sup>, 1972)